In-Wall Dehumidifier Surface Mount Kit


Part No. 4037766

Parts Included:

- **1.** Foam Tape 4" Long (x6)
- 2. Foam Tape 24" Long (x2)
- 3. Surface Mount
- **4. Screw A -** #10 Wood Screws (x5)
- **5.** Screw B #8 Sheet Metal Screws (x5)
- 6. Plastic Grommet / Drain Hose Bushing

Tools Required:

- Drill / Screwdriver
- · Long Bit Extender (optional)




Step 1. Install Foam Tape to Surface Mount Kit

Identify the front side of the surface mount kit by locating the semi-circular cutouts along the inside edge.


Install 4" foam tape to the front as shown. Do not cover holes for fastening.


Install 24" foam tape to the back as shown. Do not cover holes for fastening.













Step 4. Install In-Wall Dehumidifier to Surface Mount

Lift and support the dehumidifier by the plastic drain pan below the evaporator coil and place inside of the surface mount. Two people are recommended for this step.

Route the drain hose and electrical wiring through the corresponding knock out holes of the surface mount and dehumidifier to connect.

